



Soteria Twin Input/Output Unit Installation Guide

Item No	Part No	Product Description
4110-1103	SA4700-104AMP	Soteria Twin Input/Output Unit

Technical Information

All data is supplied subject to change without notice. Specifications are typical at 24V, 25°C and 50% RH unless otherwise stated.

Supply Voltage	17-35V dc
Quiescent Current	500µA
Power-up Surge Current	900µA
Relay Output Contact Rating	1A at 30V dc or ac
LED Current	1.6mA per LED
Maximum Loop Current (I _c max; L1 in/out)	1A
Operating Temperature	-40°C to 70°C
Humidity	0% to 95% RH (no condensation or icing)
Approvals	EN 54-17 & EN 54-18

For additional technical information please refer to data sheet PDS4110-1103 which is available on request.

Addressing

Table 1

	XP95 / Discovery Systems	Soteria CoreProtocol Systems
Segment	1	Sets the address
	2	
	3	
	4	
	5	
	6	
	7	
	8	Set to '0' (Fault value is returned if set to '1')
FS	Enables failsafe mode (compliant with BS7273-4 for door holders)	
LED	Enables/Disables LED (except Isolator LED)	

Note:
On mixed systems, addresses 127 and 128 are reserved. Refer to system's panel manufacturer for further information.

Installation

1

i Drill holes where required.

2

! Do not over tighten screws

3

i Remove knockouts and fit glands where required.

4

! Do not over tighten screws

6

i See Table 1

7

! The 8th segment must be in set to '0' for Discovery / XP95 operation

9

i Note the alignment marks

5








! Do not over tighten screws

8




! All CI tests must be completed before connecting the interface. For connectivity see Figs 1, 2 & 3

10

Address Setting Examples



Connectivity Examples



LED Status Indicator

RLY	Continuous Red	Relay Active
	Continuous Yellow	Fault
POLL/ISO	Flashing Green	Device Polled
	Continuous Yellow	Isolator Active
IP	Continuous Red	Input Active
	Continuous Yellow	Input Fault

Note:
Not all LEDs can be on simultaneously.

Commissioning

The installation must conform to BS5839-1 (or applicable local codes).

Maintenance

Removal of the external cover must be carried out using a flat screwdriver or similar tool.

Caution!

Unit damage. No electrical supply greater than 50V ac rms or 75V dc should be connected to any terminal of this Twin Input/Output Unit.

Note:

For compliance with Electrical Safety Standards the sources switched by the output relays must be limited to a 71V transient over-voltage condition. Contact Ampac for more information.

Troubleshooting

Before investigating individual units for faults, it is important to check that the system wiring is fault free. Earth faults on data loops or interface zone wiring may cause communication errors. Many fault conditions are the result of simple wiring errors. Check all connections to the unit.

Problem	Possible Cause
No response or missing	Incorrect address setting
Fault condition reported	Incorrect loop wiring
	Incorrect input wiring
Relay fails to operate	EOL resistor missing
	Incorrect wiring
Relay energised continuously	Control panel has incorrect cause and effect programming
	Incorrect loop wiring
Analogue value unstable	Incorrect address setting
	Dual address
Constant Alarm	Loop data fault, data corruption
	Incorrect wiring
Isolator LED on	Incorrect end-of-line resistor fitted
	Incompatible control panel software
	Short-circuit on loop wiring
	Wiring reverse polarity
	Too many devices between isolators

Mode Table*

Mode	Description
1	DIL Switch XP mode
2	Alarm Delays
3	Output and N/O input (can be equivalent for output only)
4	Output and N/C input
5	Output with feedback (N/C)
6	Failsafe output with feedback (N/C)
7	Failsafe output without feedback
8	Momentary input activation sets output relay
9	Input activation sets output

*Soteria CoreProtocol enabled systems only